

Liebert Air Conditioner
Monitored Points List

Status	Meters
High Head #1	Temperature
High Head #2	Humidity
Loss of Airflow	% Heating
Custom 1	% Cooling
Custom 3	% Glycol
Filter	Stages
High Temp	Temp. Setpoint
Low Temp	Temp. Tolerance
High Humidity	Humidity Setpoint
Low Humidity	Humidity Tolerance
High Water	High Temp. Set
No Water	Low Temp. Set
Comp #1OL	High Humidity Set
Comp #2OL	Low Humidity Set
Fan OL	Wsk_Delay
Manual Override	Res Delay
Smoke	Hum. Water Rate
LOWTFlow	CW Cycle
Stndby ON	IGM Clock
Low Suction	Water Rate
Sh. Cycle	
Power Loss	
Inverter Bypass	
Local #1	
Local #2	
High Hd #1	
High Hd #2	
High Hd #3	
No Water #1	
No Water #2	
No Water #3	
Hi Water T #1	
Hi Water T #2	
Hi Water T #3	
Lo Water T #1	
Lo Water T #2	
Lo Water T #3	
No Power #1	
No Power #2	
No Power #3	
H2O Fl. #1	
H2O Fl. #2	
H2O Fl. #3	