

Liebert S610 (SNMP) UPS
Monitored Points List

Status	Meters
Summary Alarm	Output Volt. AB
Inverter On	Output Volt. BC
Inverter Off	Output Volt. CA
On Bypass	Output Current A
	Output Current B
	Output Current C
	Frequency Out
	Battery Time (min)
	Battery Temp(C)
	Battery Volts
	Battery Current
	Battery Capacity
	Battery KWH
	Input Volt. AB
	Input Volt. BC
	Input Volt. CA
	Input Current A
	Input Current B
	Input Current C
	kVA Out%
	kW Out
	Bypass VAB
	Bypass VBC
	Bypass VCA
	Bypass IA
	Bypass IB
	Bypass IC