

Piller Uniblock UPS  
Monitored Points List

Status	Meters
Rectifier Failure	kVA Mains1
Output On	Frequency Mains1
Pony Motor On	Vab Mains1
Stat Switch Failure	Vbc Mains1
Stat Switch On	Vca Mains1
Rectifier On	Current A Mains1
General Fail	Current B Mains1
Mains 1 Failure	Current C Mains1
Mains 2 Failure	kVA Mains2
Control Volt Fail	Frequency Mains2
Winding HiTemp	Vab Mains2
Overload	Vbc Mains2
EPO	Vca Mains2
On Battery	Current A Mains2
Inverter On	Current B Mains2
	Current C Mains2
	Current
	Battery
	Voltage
	Battery
	Vbc Output
	Vca Output
	Current A Output
	Current B Output
	Current C Output