

Stulz ATS
Monitored Points List

Status	Meters
Hi Temp	Temperature
Lo Temp	Water Temperature
Temp Sensor	Humidity
H2O Sensor	24 hr Min Temp
H2O Low Temp	24 hr Min Humid
Humidity Sensor	24 hr Max Temp
Hi Humidity	24 hr Max Humid
Low Humidity	Temp Hi Alrm Sp
Air Proving	Temp Lo Alrm Sp
RTC	Room Sp
Buzzer Enabled	Temp Sp Max
Comp1 Hi Press	Temp Sp Min
Comp1 Low Pressure	H2O Temp Al Sp
Comp2 Hi Pressure	Humid Hi Al Sp
Comp2 Low Pressure	Humid Lo Al Sp
Temp Display Enabled	Humid Sp
Change RTC Day	Humid Max Sp
Change RTC Hour	Cooling DB
Change RTC Minute	Dehumid DB
Change RTC Month	Heating DB
Change RTC Weekday	Blower Run hr/1000
Change RTC Year	Heat Run hr/1000
Enable Nite Setback	Comp 1 hr/1000
RTC Present	Comp 2 hr/1000
Auto Restart	Humid hr/1000
Unit Rotation PM	Humid DB
Manual Rotation	
Nite Setback PM	
Custom	
Pump Failure	
Drain Failure	
Water Detected	
Blower On	
SCW Status	
Custom Alarm	
Comp1 ON	
Comp2 ON	
Heater1 ON	
Heater2 ON	
Humidifier	
Summary Status	
Filter	
Fire Stat	
Humidifier	
Smoke Detector	
System Off	