

United Power PDU
Monitored Points List

Status	Meters
A-B V HIGH	IN V_A-B
A-B V LOW	IN V_B-C
B-C V HIGH	IN V_C-A
B-C V LOW	OUT V_A-B
C-A V HIGH	OUT V_B-C
C-A V LOW	OUT V_C-A
VOUT A HIGH	Current A
VOUT A LOW	Current B
VOUT B HIGH	Current C
VOUT B LOW	Neutral Current
VOUT C HIGH	Ground Current
VOUT C LOW	Temperature
L1 CURRENT HIGH	Humidity%
L2 CURRENT HIGH	Frequency
L3 CURRENT HIGH	Total KVA
N CURRENT HIGH	%Load A
G CURRENT HIGH	%Load B
HIGH TEMP	%Load C
LOW TEMP	Total KW
HIGH HUMIDITY	KW A
LOW HUMIDITY	KW B
HIGH FREQUENCY	KW C
LOW FREQUENCY	PF A
PHASE ROTATION	PF B
PHASE LOSS	PF C
SHUTDOWN	KW-H A
TRANSFORM TEMP	KW-H B
BLDG_#3	KW-H C
BLDG_#4	PEAK DEMAND
BLDG_#5	
BLDG_#6	
BLDG_#7	
BLDG_#8	
TRANSIENT ALARM	